

Overview of versions for GEMÜ 1435 ePos

The following table allows you to identify the document version to be used for the operating instructions of the intelligent GEMÜ 1435 ePos electro-pneumatic positioner, depending on the firmware version of this device.

The reasons for the changes in the respective revised versions of the firmware are also provided here.

The firmware version of the device can be called up via the configuration menu.

Firmware version	Effective from	Version of the operating instructions	Category	Change
V1.3.1.6	March 2006	V_1_3_1_4		
V1.3.1.7	April 2006			
V1.3.1.8	November 2010			
V2.0.0.0		V_2_0_0_0	Platform conversion	
V2.0.0.1	December 2013	V_2_0_0_1		
V2.0.0.2	January 2014		Troubleshooting	
V2.0.0.3	March 2014	V_2_0_0_3	Improvement	– Initialisation routine of large-volume actuators optimized
V2.0.0.4	March 2014		Troubleshooting	– Error of wrong display of firmware version fixed – Error in incorrect assignment of valve position for NO valves eliminated
V2.0.0.5	June 2015		Improvement	– Actuation of small-volume actuators optimized
V2.0.0.6	September 2018		Adaptation	– Adaptation to the new display controller